



SPARE PARTS LIST

Height adjustment glide 645

Pos. No.	Art. No.	Spare part
1	20039	M6 nut, self-locking, stainless A2
2	20634	Machine screw, M3x14 mm, stainless, Torx PH
3	20730	Screw, Remform, 3x10 mm, Torx PH FZB
4	20837	Washer, Ø5,2x15x1,2, DIN9021
5	20897	Screw, M4x30 mm, Torx PH
6	21045	Cable passage, neoprene
7	28405	Axle spring, bottom, Ø7,5mm
8	28406	Locking device for forked shock absorber end piece
9	40043	Felt pad
10	40091	M5 nut
11	41055	Terminal block, black, female part, Wieland
12	41056	Terminal block, black, male part, Wieland
13	41069	M16 cable gland with strain relief
14	41070	M16 nut
15	41703	Bush 1,5mm ² with collar, black
16	47755	Top for terminal block, black, female part, Wieland
17	47556	Top for terminal block, black, male part, Wieland
18	64008	Handle
19	64501	Slide profile
20	64502	Bottom end profile
21	64503	Top end profile
22	64504	Top mounting bracket
23	64505	Bottom mounting bracket
24	64506	Bracket for gas spring
25	64508	Mounting plate for hair dryer
26	64509	Assembly bracket for gas springs
27	64510	Steel rod for spiral cord
28	64511	Gas spring, 60N
29	64512	Spiral cord
30	64514	Cable terminal cover, neoprene, type DA 136-6064
31	64515	Mirror
32	64520	Machine screw, M6x35 mm, stainless, Torx PH
33	64522	Screw for top and bottom, M5x16 mm, stainless





34	64527	Locknut M5, stainless A2
35	64528	Machine screw, M5x8, stainless, Torx PH
36	64529	Washer, Ø6,5x11,7x1,5, DIN125A, stainless A2
37	64530	Flange nut M6x8,5, form C, stainless A2
38	64531	Allen screw, M6x16, stainless
39	64535	Console sliding guide (2-section)
	64536	Spare parts set for replacement of gas spring